

Menu

HISTORY FILE MAP for year 1999


Realtime

Playback

Recalled Realtime

Recalled Playback

16m bad/degraded playback 512bps data due to TGC problems at DSS42. No DR raised.
Not known why telemetry recall filled holes in realtime data but not playback.



16m realtime 512 bps data lost at bit rate change due to TGC problem at DSS42. DR A04208 refers.

20m realtime 1024/2048bps data lost due to stuck subreflector at DSS42. DR A04218 refers.

10m realtime 512 bps data lost at bit rate change due to TGC problem at DSS42. DR A04225 refers.